

Title:	Shovel Potentiometer Intermediate Bdf Adjustment					
Date in:		Response:	Model:	Author:		
2006-04-03		2006-04-03	-	СМа		


## **Shovel Potentiometer Intermediate Bdf Adjustment**

#### 1 Turn unit off

Put current measurement probe at pin 15 of 25-pin D-SUB connector (handler) (C1.1)

Remove wire (wt/ye) form pin15

Insert temporary wire in pin 15



Wire to shovel motor wt/ye

Put current measurement probe between temporary wire and wire removed from pin 15 Set current measurement to +/-200mA DC

## **Questions & Answers**





StX 40/200

C HC HR DC Von Bezeichnung	Nach	Farbe		Farbe	Nach	Bezeichnung	Von
VOII DOZDIONIMANY	Tracon		D-Sub 25 polig male	,			
4.8.9 PIt Det off 4.8.3 PP Sensor +24V 4.8.20 NC GND 4.8.21 Stp Turn A1 5tp Turn B1 4.8.15 Stp Turn D1 4.8.16 Stp Lift A2 4.8.24 Stp Lift C2 4.8.25 NC	1.1.1 1.1.2 1.1.3 1.1.4 1.1.5 1.1.6 1.1.7 1.1.8 1.1.9 1.1.10 1.1.11 1.1.12	wtpk wtbk  rd  bu pk wtgy wtgn rdbu ye gn	0 <sup>1</sup> 0 <sup>14</sup> 0 <sup>2</sup> 0 <sup>15</sup> 0 <sup>3</sup> 0 <sup>16</sup> 0 <sup>4</sup> 0 <sup>16</sup> 0 <sup>4</sup> 0 <sup>17</sup> 0 <sup>5</sup> 0 <sup>18</sup> 0 <sup>6</sup> 0 <sup>19</sup> 0 <sup>7</sup> 0 <sup>20</sup> 0 <sup>8</sup> 0 <sup>21</sup> 0 <sup>9</sup> 0 <sup>21</sup> 0 <sup>10</sup> 0 <sup>22</sup> 0 <sup>10</sup> 0 <sup>23</sup> 0 <sup>11</sup> 0 <sup>23</sup> 0 <sup>12</sup> 0 <sup>24</sup> 0 <sup>12</sup> 0 <sup>24</sup> 0 <sup>12</sup> 0 <sup>25</sup> 0 <sup>13</sup> 0 <sup>25</sup> 0 <sup>13</sup> 0 <sup>25</sup>	- wtye bngn gy bk vt gybn gypk - yebn bn wt	1.1.14 1.1.15 1.1.16 1.1.17 1.1.18 1.1.19 1.1.20 1.1.21 1.1.22 1.1.23 1.1.24 1.1.25	NC Mot Shvl - Mot Shvl + Sw Turn IN Shvl Front Shvl Back Turn Safe Z-Lift 0  Plt Det 1 Stp Lift B2 Stp Lift D2	- 4.8.13 4.8.14 4.8.23 4.8.19 4.8.17 - 4.8.17 - 4.8.26 4.8.26

Steckeransicht von Bestückungs Seite

# LICONIC INSTRUMENTS

### **Questions & Answers**

- 2 Turn speed pot to minimum speed CCW Turn torque pot to minimum CCW
- 3 Manually position lift wagon so shovel can freely extend
- 4 Turn unit on Check current reading should be approx. 10mA
- 5 Start StxCyt32 program and select option 1 Terminal
- 6 Read T48 "RD T48" returns "1,aaaaa,sssss" and remember third value (e. g. 1,00045,00045)
- 7 Set T48 to zero "WS T48 0" returns "OK"
- 8 Go in Option 5 Component Test, Option 6 Shovel Movement, Delay = 5 s
- 9 Gradually open speed pot (CW) until shovel takes approximately 2 seconds for entire travel path
- 10 Stop shovel manually in the middle of the shovel travel path
  While holding shovel in its center position gradually increase current CW until current rises
  Gradually lower current (CCW) until current starts decreasing
- 11 Check shovel motion for smooth running also, manually stop shovel at several positions and check for safe start of motion
- 12 Exit Component Test program
- 13 Enter Terminal (Option 1)
  Enter Service Mode "WR DM123 63450"
  ST 1701 shovel out
  RS 1701 shovel in
- 14 Adjust T48 by gradually increasing its value (e.g. WS T48 45, WS T48 50 ... ) until shovel motion is fast until shortly before shovel reaches end position.
- 15 Exit service mode "WR DM123 0"