

Title:	STX1000 Lifter TPM Connector			ID:
				0021
Date in:	Response:	Model:	Author:	
2007-06-12	2007-06-12	STP1000	CMa	

STP1000-DFSA Former Lifter / TPM Connector

Attached pictures show lifter resp. TPM connector of early STX1000-DFSA systems. These type connectors were replaced. All units should have these connectors replaced since operation with old connectors may cause unreliable operation.

1st series Lifter Connector (must be replaced)



1st series TPM Connector (must be replaced)





New / Current
Lifter / TPM
Connector