

Title:	Noisy Gate	ID:	
		0162	
Date in:	Response:	Model:	Author:
2006-06-02	2006-06-02	-	CMa

Q:

On incubator two on system 3 the door mechanism seems to be excessively noisy. I have lubricated the nylon gear mechanism, and the bearing guides. I feel that the door motor may be the cause of the noise. Could you possibly send me a motor and instructions on fitting it to the incubator.

A:

Some "old"-design Gates are noisier than others. No impact on lifetime is known.