

Title:	RS232 Connector Layout	ID:	
		<i>0301</i>	
Date in:	Response:	Model:	Author:
<i>2004-03-19</i>	<i>2004-03-19</i>	<i>LDR</i>	<i>CMa</i>

Q:

The engineering guys here on site have put in some work to get the third Tecan carousel unit functioning, we had it all working fine until yesterday when we lost comes between the PC and the carousel. We have checked the com link between the PC and the carousel and the signal is definitely getting as far as the RS232 connection. When we take off the cover there is an interface between the RS232 and the PLC (fitted to cut out interference from a Genesis). We are not sure if the comes problem is between the RS232 and the interface or from the interface to the PLC. Could you send a circuit diagram of interface so that we can check the comes link all the way to the PLC?

A:

Tecan - Handler

