

Title:	Cooling does not work			ID:
				0063
Date in:	Response:	Model:	Author:	
2006-08-18	2006-08-18	STX1000	CMa	

Q:

On an STX1000-DFSA (Deep Freezer) we have +38'C.

A:

First set of information

- What is the temperature on the lower display?
- Does the compressor run?
- Check Overpressure Switch
- Does blower inside chamber run
- Is Relay 515 activated
- Is Relay 513 activated

